

Technician Unpaid Jobs Report

07/20/2010

Technician Details	
joe bodywork	
Departments	Disassembly, Body, Reassembly
Unpaid Jobs	3
Unpaid Hours	74.1
Scheduled Hours	74.1

RO	Customer	Insurance	Estimator	Year	Make	Model	Color	Tag#	Due	Status
27341	Demo Owner 9	Bear River Mutua...	Lee Hasley	02	Honda	Accord	BLUE M	6609S	07/22/10	Body
	Labor Type	Complete	Task Hours	Hours Paid	Actual Hours	Notes				
	Body	No	22.5	0	0					

RO	Customer	Insurance	Estimator	Year	Make	Model	Color	Tag#	Due	Status
1005	Demo Insured 7	No Data	Lee Hasley	03	TOYO	TACOMA 4X4 DOUBL...		No Data	07/27/10	Body
	Labor Type	Complete	Task Hours	Hours Paid	Actual Hours	Notes				
	Body	No	20.3	0	0					

RO	Customer	Insurance	Estimator	Year	Make	Model	Color	Tag#	Due	Status
1002	Demo Insured	ALLSTATE INSURAN...	Jim Epsilon	04	ACUR	MDX 4X4 TOURING	GREY	LFA-283	07/27/10	Body
	Labor Type	Complete	Task Hours	Hours Paid	Actual Hours	Notes				
	Body	No	31.3	0	0					